

AXIAL FLUX PERMANENT MAGNET BRUSHLESS MACHINES

Jacek F. Gieras, Rong-Jie Wang and Maarten J. Kamper
Kluwer Academic Publishers, Boston-Dordrecht-London, 2004

TABLE OF CONTENTS

	page
Preface	v
1. Introduction	1
1.1. Scope	1
1.2. Features	1
1.3. Development of AFPM machines	3
1.4. Types of axial flux PM machines	4
1.5. Topologies and geometries	6
1.6. Axial magnetic field excited by PMs	10
1.7. PM eddy-current brake as the simplest AFPM brushless machine	13
1.8. AFPM machines versus RFPM machines	16
1.9. Power limitation of AFPM machines	19
Numerical examples	19
2. Principles of AFPM machines	27
2.1. Magnetic circuits	27
2.1.1. Single-sided machines	27
2.1.2. Double-sided machines with internal PM disc rotor	27
2.1.3. Double-sided machines with internal ring-shaped core stator	29
2.1.4. Double-sided machines with internal slotted stator	31
2.1.5. Double-sided machines with internal coreless stator	32
2.1.6. Multidisc machines	33
2.2. Windings	33
2.2.1. Three-phase windings distributed in slots	35
2.2.2. Drum-type winding	35
2.2.3. Coreless stator winding	37
2.2.4. Salient pole windings	37
2.3. Torque production	38
2.4. Magnetic flux	40
2.5. Electromagnetic torque and EMF	41
2.6. Losses and efficiency	42
2.6.1. Stator winding losses	42
2.6.2. Stator core losses	44
2.6.3. Core loss finite element model	46
2.6.4. Losses in permanent magnets	46
2.6.5. Rotor core losses	48
2.6.6. Eddy current losses in stator conductors	49
2.6.7. Rotational losses	50

2.6.8. Losses for nonsinusoidal current	51
2.6.9. Efficiency	51
2.7. Phasor diagrams	52
2.8. Sizing equations	55
2.9. Armature reaction	58
2.10. AFPM motor	62
2.10.1. Sine-wave motor	62
2.10.2. Square-wave motor	63
2.11. AFPM synchronous generator	67
2.11.1. Performance characteristics of a stand alone generator	67
2.11.2. Synchronization with utility grid	68
Numerical examples	70
3. Materials and fabrication	81
3.1. Stator cores	81
3.1.1. Non-oriented electrical steels	81
3.1.2. Amorphous ferromagnetic alloys	85
3.1.3. Soft magnetic powder composites	85
3.1.4. Fabrication of stator cores	89
3.1.4.1. Fabrication of laminated stator cores	89
3.1.4.2. Fabrication of soft magnetic powder stator cores	90
3.2. Rotor magnetic circuits	91
3.2.1. PM materials	92
3.2.2. Characteristics of PM materials	98
3.2.2.1. Alnico	98
3.2.2.2. Ferrites	99
3.2.2.3. Rare-earth permanent magnets	100
3.2.3. Operating diagram	103
3.2.4. Permeances for main and leakage fluxes	106
3.2.5. Calculation of magnetic circuits with PMs	110
3.2.6. Fabrication of rotor magnetic circuits	112
3.2.6.1. Halbach array	114
3.3. Windings	115
3.3.1. Conductors	115
3.3.2. Fabrication of slotted windings	116
3.3.3. Fabrication of coreless windings	117
Numerical examples	119
4. AFPM machines with iron cores	127
4.1. Geometries	127
4.2. Commercial AFPM machines with stator ferromagnetic cores	128
4.3. Some features of iron-cored AFPM machines	130
4.4. Magnetic flux density distribution in the air gap	130
4.5. Calculation of reactances	133
4.5.1. Synchronous and armature reaction reactances	133
4.5.2. Stator leakage reactance	133
4.6. Performance characteristics	137
4.7. Performance calculation	137
4.7.1. Sine-wave AFPM machine	137

4.7.2. Synchronous generator	141
4.7.3. Square-wave AFPM machine	143
4.8. Finite element calculations	144
Numerical examples	146
5. AFPM machines without stator cores	157
5.1. Advantages and disadvantages	157
5.2. Commercial coreless stator AFPM machines	157
5.3. Performance calculation	159
5.3.1. Steady-state performance	159
5.3.2. Dynamic performance	161
5.4. Calculation of coreless winding inductances	163
5.4.1. Classical approach	163
5.4.2. FEM approach	164
5.5. Performance characteristics	166
5.6. Eddy current losses in the stator windings	168
5.6.1. Eddy current loss resistance	168
5.6.2. Reduction of eddy current losses	171
5.6.3. Reduction of circulating current losses	173
5.6.4. Measurement of eddy current losses	174
5.7. Armature Reaction	176
5.8. Mechanical design features	178
5.8.1. Mechanical strength analysis	179
5.8.1.1. Attraction force between rotor discs	179
5.8.1.2. Optimum design of rotor discs	180
5.8.2. Imbalanced axial force on the stator	182
5.9. Thermal problems	184
Numerical examples	184
6. AFPM machines without stator and rotor cores	195
6.1. Advantages and disadvantages	195
6.2. Topology and construction	195
6.3. Air gap magnetic flux density	198
6.4. Electromagnetic torque and EMF	199
6.5. Commercial coreless AFPM motors	200
6.6. Case study: low-speed AFPM coreless brushless motor	202
6.6.1. Performance characteristics	202
6.6.2. Cost analysis	204
6.6.3. Comparison with cylindrical motor with laminated stator and rotor cores	205
6.7. Case study: low-speed coreless AFPM brushless generator	206
6.8. Characteristics of coreless AFPM machines	208
Numerical examples	211
7. Control	219
7.1. Control of trapezoidal AFPM machine	219
7.1.1. Voltage equations	220
7.1.2. Solid-state converter	222

7.1.3. Current control	225
7.1.4. Speed control	228
7.1.5. High speed operation	229
7.2. Control of sinusoidal AFPM machine	230
7.2.1. Mathematical model and ω equivalent circuits	230
7.2.2. Current control	236
7.2.3. Speed control	237
7.2.4. Hardware of sinusoidal AFPM machine drive	241
7.3. Sensorless position control	243
Numerical examples	245
8. Cooling and Heat Transfer	257
8.1. Importance of thermal analysis	257
8.2. Heat transfer modes	257
8.2.1. Conduction	258
8.2.2. Radiation	258
8.2.3. Convection	259
8.2.3.1. Convection heat transfer in disc systems	260
8.3. Cooling of AFPM machines	263
8.3.1. AFPM machines with self-ventilation	263
8.3.1.1. The ideal radial channel	263
8.3.1.2. The actual radial channel	266
8.3.1.3. Characteristics	269
8.3.1.4. Flow and pressure measurements	270
8.3.2. AFPM machines with external ventilation	272
8.3.2.1. External fans	272
8.3.2.2. Heat pipes	274
8.3.2.3. Direct water cooling	275
8.4. Lumped parameter thermal model	276
8.4.1. Thermal equivalent circuit	276
8.4.2. Conservation of energy	278
8.5. Machine duties	279
8.5.1. Continuous duty	279
8.5.2. Short-time duty	279
8.5.3. Intermittent duty	280
Numerical examples	281
9. Applications	289
9.1. Power generation	289
9.1.1. High speed generators	289
9.1.2. Low speed generators	291
9.2. Electric vehicles	293
9.2.1. Hybrid electric vehicles	294
9.2.2. Battery electric vehicles	298
9.3. Ship propulsion	300
9.3.1. Large AFPM motors	300
9.3.2. Propulsion of unmanned submarines	301
9.3.3. Counterrotating rotor marine propulsion system	302

9.4. Electromagnetic aircraft launch system	303
9.5. Mobile drill rigs	305
9.6. Elevators	308
9.7. Miniature AFPM brushless motors	311
9.8. Vibration motors	313
9.9. Computer hard disc drives	315
Numerical examples	316
Symbols and Abbreviations	321
References	331
Index	336